

# Tekniske tegninger


Tre/alu, 2-lags glass - 68 & 80mm karmdybde

A close-up photograph of a window frame and sill. The frame is dark-colored, and the sill is white. The window is partially open, showing a view of a white wall. The image is positioned on the right side of the page, partially overlapping a teal background and a yellow diagonal stripe.


**SPAREVINDUER**

# 2-veis vindu, innoverslående


3-lags glass, 80mm karmdybde, Tre/alu





Overkarm




Bunramme




Sidekarm



Tverrpost



Bunnkarm



25 mm Energisprosse



+47 66 90 03 03







post@sparevinduer.no

**SPAREVINDUER**

# Smal fastkarm

3-lags glass, 80mm karmdybde, Tre/alu



+47 66 90 03 03









post@sparevinduer.no

**SPAREVINDUER**

# 2-veis dør, innoverslående

3-lags glass, 80mm karmdybde, Tre/alu



+47 66 90 03 03










post@sparevinduer.no

**SPAREVINDUER**

# 2-veis vindu, innoverslående

## 3-lags glass, 92mm karmdybde, Tre/alu



+47 66 90 03 03







post@sparevinduer.no

**SPAREVINDUER**

# Smal fastkarm

3-lags glass, 92mm karmdybde, Tre/alu



+47 66 90 03 03




post@sparevinduer.no


**SPAREVINDUER**

# 2-veis dør, innoverslående


3-lags glass, 92mm karmdybde, Tre/alu




Overkarm




Midt dobbeldør




25 mm Energisprosse



Sidekarm



Tre bunnkarm



Alu bunnkarm



+47 66 90 03 03



post@sparevinduer.no

**SPAREVINDUER**